



REVISED CONSTRUCTION ALERT
May 9, 2016

CONTACT: Tommy Williamson
(817) 914-0543
twilliamson@ferrovial.us

**NEW DIRECT CONNECTOR FROM WESTBOUND 820 TO NORTHBOUND 35W
OPENS MAY 10; CONNECTOR TO SOUTHBOUND 35W TO CLOSE MAY 9**

FORT WORTH, Texas – On **Tuesday, May 10**, the new direct connector from westbound I-820 to northbound I-35W will open. **This new direct connector is located prior to the existing exit**, and is part of a split exit for both northbound and southbound I-35W. Drivers heading northbound will exit right; drivers heading southbound will exit to the left.

As part of this activity, contractors will **close the exit from westbound I-820 to southbound I-35W from Monday, May 9 at 9 p.m. until Tuesday, May 10 at 5 a.m.** Traffic will be redirected to FM 156.

"This new direct connector is in a different configuration than drivers are used to, so we strongly encourage caution through this area," said Heather DeLapp, regional public relations manager for North Tarrant Infrastructure, the project contractor.

This work is part of the \$1.4 billion North Tarrant Express 35W project. This includes a section that is currently ranked number six on the state's most congested roadway list along 6.5 miles of I-35W from north of I-30 to north of I-820 including the I-35W/I-820 interchange in Fort Worth. The project includes the reconstruction of main lanes and the addition of TEXpress managed lanes.

Drivers are encouraged to "Know Before They Go," and visit www.northtarrantexpress.com for upcoming closures. To view detour maps, please visit the [Alternate Route Map](#) page of our website. Also, as our lane closures are updated frequently, please visit the [Lane Closures](#) page on our website daily for the most current information. Closures are subject to weather conditions, and construction activities may be postponed if necessary.

###

NEW DIRECT CONNECTOR FROM WESTBOUND 820 TO NORTHBOUND 35W

Monday, May 9 at 9 p.m. to 5 a.m. Tuesday, May 10



The existing direct connector from westbound I-820 to northbound I-35W will be closed.

The new direct connector is located prior to the existing exit, and is part of a split exit for both northbound and southbound I-35W.

Please note: The direct connector from westbound I-820 to southbound I-35W will be closed.

Traffic will be redirected to FM 156.