

CONSTRUCTION ALERT September 16, 2016

CONTACT: Tommy Williamson

(817) 914-0543

twilliamson@ferrovial.us

FULL DIRECT CONNECTOR AND INTERCHANGE CLOSURES SCHEDULED AT I-820/I-35W THIS WEEKEND

FORT WORTH, Texas – Motorists should expect full direct connector and interchange closures at I-820/I-35W this weekend. A complete list of closures and traffic redirections is as follows:

Friday, September 16, 9 p.m. to 10 a.m.

- All lanes of eastbound I-820 at the I-35W/I-820 interchange will be closed. Traffic will be redirected along the frontage road to Meacham Boulevard.
- The direct connector from southbound I-35W to eastbound I-820 will be closed. Traffic will be redirected to Meacham Boulevard.

Saturday, September 17, 9 p.m. to 10 a.m.

- All lanes of eastbound I-820 at the I-35W/I-820 interchange will be closed. Traffic will be redirected along the frontage road to Meacham Boulevard.
- The direct connector from southbound I-35W to eastbound I-820 will be closed. Traffic will be redirected to Meacham Boulevard.


This work is weather-permitting. **Updated closure information is posted daily** on Twitter (oNTExpress) and Facebook (facebook.com/northtarrantexpress).

This work is part of the \$1.4 billion North Tarrant Express 35W project. This includes a section that is currently ranked number six on the state's most congested roadway list along 6.5 miles of I-35W from north of I-30 to north of I-820 including the I-35W/I-820 interchange in Fort Worth. The project includes the reconstruction of main lanes and the addition of TEXpress managed lanes.

Drivers are encouraged to "Know Before They Go," and visit www.northtarrantexpress.com for upcoming closures. To view detour maps, please visit the Alternate Route Map page of our website. Also, as our lane closures are updated frequently, please visit the Lane Closures page on our website daily for the most current information. Closures are subject to weather conditions, and construction activities may be postponed if necessary.



EASTBOUND I-820 CLOSURES AT I-35W/I-820 INTERCHANGE



All lanes of eastbound IH 820 at the I-35W/IH 820 interchange will be closed. Traffic will be redirected along the frontage road to Meacham Blvd.

The direct connector from southbound I-35W to eastbound IH 820 will be closed.

Traffic will be redirected to Meacham Blvd.